

ALL “Surgery-Ready” suction tips contained residual blood, bone, tissue or rust.



Poor design makes some tools impossible to clean. Researchers found all 350 surgery-ready suction tips contained blood, bone, tissue or rust, and many were packed with debris.